

## EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	201846	(disk adj drive) hdd hdsd hds hda hdda (hard near2 drive)	US-PGPUB; USPAT	OR	ON	2006/05/15 16:43
L2	4	1 and ((gimble flexture) near10 dimple)	US-PGPUB; USPAT	OR	ON	2006/05/15 16:02
L3	167	1 and (gimble flexture)	US-PGPUB; USPAT	OR	ON	2006/05/15 16:43
L4	4012	(load adj beam) loadbeam	US-PGPUB; USPAT	OR	ON	2006/05/15 16:44
L5	65	3 and 4	US-PGPUB; USPAT	OR	ON	2006/05/15 16:06
L6	328819	((sens\$4 detect\$4) near10 (accel\$ vibrat\$ strain pressure)) pzt\$1 piezo\$	US-PGPUB; USPAT	OR	ON	2006/05/15 16:44
L7	39	3 and 6	US-PGPUB; USPAT	OR	ON	2006/05/15 16:09
L8	4780	1 and (gimble flexture)	US-PGPUB; USPAT	OR	ON	2006/05/15 16:10
L9	1717	4 and 8	US-PGPUB; USPAT	OR	ON	2006/05/15 16:09
L10	311	6 and 9	US-PGPUB; USPAT	OR	ON	2006/05/15 16:10
L11	291	10 and slider	US-PGPUB; USPAT	OR	ON	2006/05/15 16:10
L12	103	11 and dimple	US-PGPUB; USPAT	OR	ON	2006/05/15 16:10
L13	193	laminat\$4 near3 (gimble flexture)	US-PGPUB; USPAT	OR	ON	2006/05/15 16:44
L14	14	10 and 13	US-PGPUB; USPAT	OR	ON	2006/05/15 16:11
L15	80773	(disk adj drive) hdd hdsd hds hda hdda (hard near2 drive)	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 16:43
L16	360353	((sens\$4 detect\$4) near10 (accel\$ vibrat\$ strain pressure)) pzt\$1 piezo\$	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 16:44
L17	2121	(load adj beam) loadbeam	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 16:44
L18	40	laminat\$4 near3 (gimble flexture)	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 16:44

## EAST Search History

L19	12792	(gimble flexure)	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 16:45
L20	9	15 and 16 and 17 and 19	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 16:45
L21	45	15 and 16 and 19	EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/05/15 16:45